

March 16, 2022

Completion of Measures Implemented against Soil Contamination at the Tarui Plant

Nabtesco Corporation (headquarters: Chiyoda-ku, Tokyo; President & CEO: Katsuhiko Teramoto) hereby announces the completion of measures implemented against soil contamination detected at its Tarui Plant, including excavating and removing contaminated soil and then refilling using appropriately tested soil. Specifically, as notified in the news releases dated September 27 and October 18, 2021, soil contamination had been detected at the former site of the surface processing facility for aircraft equipment located on the premises of the Tarui Plant (Gifu Prefecture). In the underground water quality test carried out after the completion of measures to verify their effect, it was confirmed that the amounts of fluorine and hexavalent chromium were below the upper limit set in the standards for underground water quality. Accordingly, the company submitted a report on completion of the measures to Gifu Prefecture on March 16, 2022, and the report was officially accepted.

We would like to express our deep apologies to the local residents and all other related parties for the concern caused by the detection of the soil contamination and the measures implemented against it, and would thank them for their kind support with regard to implementation of the measures.

【Website of Gifu Prefecture】 (Japanese text only)

<https://www.pref.gifu.lg.jp/site/pressrelease/181569.html>

【Notification made on September 27, 2021】

Notification of the Results of the Voluntary Soil Contamination Investigation Conducted at Nabtesco Corporation's Tarui Plant

<https://www.nabtesco.com/pdf/33006e3374b116e2e74846e9b06e4dab.pdf>

【Notification made on October 18, 2021】

Follow-up Report on Soil Contamination at the Tarui Plant: Meeting the Environmental Standards for Underground Water in the Test Conducted by Gifu Prefecture at Neighborhood Wells

<https://www.nabtesco.com/pdf/c73c59337b3add7602cea9fb710be6f6.pdf>

End